

DINAMIKA MUARA SUNGAI

Muara Sungai

- Fungsi
 - Outlet sungai
 - Navigasi kapal
- Permasalah
 - Penutupan muara sungai oleh sedimen

Muara Sungai


- Contoh kasus
 - Muara Sungai Progo di Yogyakarta

MUARA K. PROGO

Stabilisasi Muara

*Foto dan Naskah
Istiarto*

Peta Rupa Bumi 1999



E 110°11'00"

11'30"

12'00"

12'30"

13'00"

13'30"

14'00'


14'30"




Pointer 7°58'50.47" S 110°12'25.25" E elev 3 ft

Streaming ||||| 100%
Image © 2007 DigitalGlobe
© 2007 Europa Technologies

Eye alt 6785 ft



Desain BCEOM



Jetty Alternatif

(Arief Nuryanto & Nur Yuwono, 2002)

Foto Udara 13 Januari 2001






Foto Udara 7 April 2004



Konstruksi dilaksanakan 2005



INDIAN OCEAN



Scour Blanket

East Jet

	MINISTRY OF SETTLEMENT AND REGIONAL INFRASTRUCTURE DIRECTORATE GENERAL OF WATER RESOURCES SOUTH JAWA FLOOD CONTROL SECTOR PROJECT	SCALE -
	BECOM and Associates	Date Oct. 2
OPANPROD9 SUB-PROJECT - PROGO RIVER BASIN PLAN OF EAST AND WEST JETTY		
DESIGNED BY	REVIEWED BY	APPROVED BY
DESIGNER	REVIEWER	APPROVING AUTHORITY
DR. IR. HENDRIK HARJO	DR. IR. HENDRIK HARJO	DR. IR. HENDRIK HARJO

MUARA K. PROGO

Maret 2005





lidah pasir

S. Progo







MUARA K. PROGO

Maret 2006



rubble mount jetty di sisi kanan
bobot batu lapis lindung 1-2 ton



rubble mount jetty di sisi kanan
bobot batu lapis lindung 1-2 ton



Jetty di sisi kiri





jetty di sisi kiri

inner jetty (rubble mount):
tinggal bagian ekor,
bagian ujung telah hilang.

jetty di sisi kiri



muara
K. Progo



inner jetty (rubble mount):
tinggal bagian ekor,
bagian ujung telah hilang.

muara
K. Progo

laut



MUARA K. PROGO

Mei 2006



Muara menyempit



16.05.2006



Maret 2006



Mei 2006





Maret 2006

Mei 2006

Jetty di sisi kanan





Terima kasih

16.05.2006